12.8 A						
Addin	A&S MOTORCYCLE PARTS,		Repair Order Invoice			
1125A Orlando Ave. Roseville, CA 95661- (800)689-9893			R/O Number: 999058361			
			Invoice Number:	99666471		
			Cashier:	VALERIE MACKEY		
				1/6/2011		
			Date Promised:	1/4/2011		
Repair Order For:		Description:				
FENDER, NATHAN						
			"Maren			
Inits For This Repair	Order		Service Writer: TIM WH	IALEN		
Year Make	Model	VIN/Serial No.	Plate	Key Board	Miles	
009 BMW	K1300GT	WB10539019ZV96537	20E2902 3	317	1963	
REAR SPRING S		E NELAT LEVER UN		1		
Part Number	Quantity Description		Each Pric	e Extension		
33538522637	1 RECALL RE					
		PAIR SET RELAY LEVER	Warrant			
		PAIR SET RELAY LEVER	Warrant Parts Subtotal	ty Warranty Warranty		
Labor				Warranty		
Description	Job Code	e Technician		Warranty Line Total		
	Job Code	e Technician	Parts Subtotal	Warranty Line Total Warranty		
Description RENEW RELAY L	Job Code LEVER 0060235	e Technician RYAN HILDEBRAND - W		Warranty Line Total		
Description RENEW RELAY L	Job Code LEVER 0060235 ons	e Technician RYAN HILDEBRAND - W Resolution	Parts Subtotal Labor Subtotal	Warranty Line Total Warranty		
Description RENEW RELAY L	Job Code LEVER 0060235	e Technician RYAN HILDEBRAND - W	Parts Subtotal Labor Subtotal	Warranty Line Total Warranty		
Description RENEW RELAY L	Job Code LEVER 0060235 ons	e Technician RYAN HILDEBRAND - W Resolution	Parts Subtotal Labor Subtotal	Warranty Line Total Warranty		
Description RENEW RELAY L Recommendation FRONT BRAKE	Job Code LEVER 0060235 ons PADS / MILES OUT 19641	e Technician RYAN HILDEBRAND - W Resolution 389.95 OK TV	Parts Subtotal Labor Subtotal W NF 1-4-11	Warranty Line Total Warranty Warranty		
Description RENEW RELAY L Recommendation FRONT BRAKE	Job Code LEVER 0060235 ons	e Technician RYAN HILDEBRAND - W Resolution 389.95 OK TV	Parts Subtotal Labor Subtotal W NF 1-4-11	Warranty Line Total Warranty Warranty		
Description RENEW RELAY L Recommendation FRONT BRAKE	Job Code LEVER 0060235 ons PADS / MILES OUT 19641 8K SERVICE 2008+ W/ VAI	e Technician RYAN HILDEBRAND - W Resolution 389.95 OK TV	Parts Subtotal Labor Subtotal W NF 1-4-11	Warranty Line Total Warranty Warranty		
Description RENEW RELAY L Recommendation FRONT BRAKE Job For: 20 Description	Job Code LEVER 0060235 ons PADS / MILES OUT 19641 8K SERVICE 2008+ W/ VAI	e Technician RYAN HILDEBRAND - W Resolution 389.95 OK TV	Parts Subtotal Labor Subtotal W NF 1-4-11	Warranty Line Total Warranty Warranty		
Description RENEW RELAY L Recommendation FRONT BRAKE Job For: 20 Description	Job Code LEVER 0060235 ons PADS / MILES OUT 19641 8K SERVICE 2008+ W/ VAI 009 BMW K1300GT WB10539019	e Technician RYAN HILDEBRAND - W Resolution 389.95 OK TV	Parts Subtotal Labor Subtotal W NF 1-4-11	Warranty Line Total Warranty Warranty		
Description RENEW RELAY L Recommendation FRONT BRAKE Job For: 20 Description C/S HE WOULD L Parts	Job Code LEVER 0060235 ons PADS / MILES OUT 19641 8K SERVICE 2008+ W/ VAI 009 BMW K1300GT WB10539019 LIKE A 18K SERVICE 2008+ W/ VA	e Technician RYAN HILDEBRAND - W Resolution 389.95 OK TV	Parts Subtotal Labor Subtotal W NF 1-4-11 Job Subtotal	Warranty Line Total Warranty Warranty Warranty		
Description RENEW RELAY L Recommendation FRONT BRAKE Job For: 20 Description C/S HE WOULD L Parts Part Number	Job Code 0060235 ons PADS / MILES OUT 19641 8K SERVICE 2008+ W/ VAI 009 BMW K1300GT WB10539019 LIKE A 18K SERVICE 2008+ W/ VAI Quantity Description	e Technician RYAN HILDEBRAND - W Resolution 389.95 OK TV LVE CK ALVE CK	Parts Subtotal Labor Subtotal W NF 1-4-11 Job Subtotal Each Price	Warranty Line Total Warranty Warranty Warranty		
Description RENEW RELAY L Recommendation FRONT BRAKE Job For: 20 Description C/S HE WOULD L Parts Part Number CLEANER	Job Code LEVER 0060235 ons PADS / MILES OUT 19641 8K SERVICE 2008+ W/ VAL 009 BMW K1300GT WB10539019 LIKE A 18K SERVICE 2008+ W/ VAL Quantity Description 7 CHEMICALS	e Technician RYAN HILDEBRAND - W Resolution 389.95 OK TV	Parts Subtotal Labor Subtotal W NF 1-4-11 Job Subtotal	Warranty Line Total Warranty Warranty Warranty Ce Extension 00 \$7.00		
Description RENEW RELAY L Recommendation FRONT BRAKE Job For: 20 Description C/S HE WOULD L Parts Part Number	Job Code LEVER 0060235 ons PADS / MILES OUT 19641 8K SERVICE 2008+ W/ VAI 009 BMW K1300GT WB10539019 LIKE A 18K SERVICE 2008+ W/ V/ Quantity Description 7 CHEMICALS 1 OIL CHANG	e Technician RYAN HILDEBRAND - W Resolution 389.95 OK TV LVE CK DZV96537 ALVE CK	Parts Subtotal Labor Subtotal W NF 1-4-11 Job Subtotal Each Pric \$1.0	Warranty Line Total Warranty Warranty Warranty Warranty		
Description RENEW RELAY L Recommendation FRONT BRAKE Job Tor: 20 Description C/S HE WOULD L Parts Part Number CLEANER 541 KOIL	Job Code LEVER 0060235 ons PADS / MILES OUT 19641 8K SERVICE 2008+ W/ VAI 009 BMW K1300GT WB10539019 LIKE A 18K SERVICE 2008+ W/ V/ Quantity Description 7 CHEMICALS 1 OIL CHANG	E Technician RYAN HILDEBRAND - W Resolution 389.95 OK TV LVE CK 2V96537 ALVE CK S AND CLEANERS E SPECIAL K BIKE LATE	Parts Subtotal Labor Subtotal W NF 1-4-11 Job Subtotal Each Pric \$1.0 \$17.5	Warranty Line Total Warranty Warranty Warranty Warranty		
Description RENEW RELAY L Recommendation FRONT BRAKE Job For: 20 Description C/S HE WOULD L Parts Part Number CLEANER 541KOIL	Job Code LEVER 0060235 ons PADS / MILES OUT 19641 8K SERVICE 2008+ W/ VAI 009 BMW K1300GT WB10539019 LIKE A 18K SERVICE 2008+ W/ V/ Quantity Description 7 CHEMICALS 1 OIL CHANG	E Technician RYAN HILDEBRAND - W Resolution 389.95 OK TV LVE CK 2V96537 ALVE CK S AND CLEANERS E SPECIAL K BIKE LATE	Parts Subtotal Labor Subtotal NNF 1-4-11 Job Subtotal Each Pric \$1.0 \$17.9 \$21.5	Warranty Line Total Warranty Warranty Warranty Warranty		
Description RENEW RELAY L Recommendation FRONT BRAKE Job For: 20 Description C/S HE WOULD L Parts Part Number CLEANER 541KOIL	Job Code LEVER 0060235 ons PADS / MILES OUT 19641 8K SERVICE 2008+ W/ VAI 009 BMW K1300GT WB10539019 LIKE A 18K SERVICE 2008+ W/ V/ Quantity Description 7 CHEMICALS 1 OIL CHANG	E Technician RYAN HILDEBRAND - W Resolution 389.95 OK TV LVE CK 2V96537 ALVE CK S AND CLEANERS E SPECIAL K BIKE LATE	Parts Subtotal Labor Subtotal NNF 1-4-11 Job Subtotal Each Pric \$1.0 \$17.9 \$21.5	Warranty Line Total Warranty Warranty Warranty Warranty	Page 1	

Job: 18K SERVICE 2008+ W/ VALVE CK (Continued)

Job For: 2009 BMW K1300GT WB10539019ZV96537

Labor Description Job Code Technician Line Total INSPECTION I RH Tech 25 \$115.00 SAFETY INSPECTION RH Tech 25 \$0.00 VALVE CK RH Tech 25 \$162.96 WARRANTY OVERLAP RH Tech 25 (\$7.28) Labor Subtotal \$270.68

Recommendations

Resolution

SPARK PLUGS AND COOLANT SUPPLIED AT N/C

Repair Order Subtotal

	Other Charges	
\$4.00	Hazmat Fee	
\$299.62	Job Subtotal	

Job: BRAKE FLUSH

Job For: 2009 BMW K1300GT WB10539019ZV96537

Description

Parts		
Part Number Quantity Description	Each Price	Extension
81220142156.5 1 BRAKE FLUID 355 M/FORCE QTY.12	\$4.50	\$4.50
	Parts Subtotal	\$4.50
Labor		
Description Job Code Technician		Line Total
BRAKE FLUSH RH Tech 25		\$81.48
	Labor Subtotal	\$81.48
	Other Charges	
	Hazmat Fee	\$1.00
	Job Subtotal	\$86.98
	Customer Job Totals	
	Parts	\$29.44
	Labor	\$352.16
	Other	\$5.00
То	tal of Customer Jobs	\$386.60

\$386.60

Sales Tax	\$2.43
Repair Order Total	\$389.03
Total Amount Due	\$389.03
Tendered: PARTS Cash	\$389.03
Change Due	\$0.00

I HEREBY AUTHORIZE THE ABOVE REPAIR WORK TO BE DONE ALONG WITH NECESSARY MATERIALS. YOU AND YOUR EMPLOYEES MAY OPERATE ABOVE VEHICLE FOR PURPOSES OF TESTING, INSPECTION OR DELIVERY AT MY RISK. AN EXPRESS MECHANIC'S LIEN IS ACKNOWLEDGED ON ABOVE VEHICLE TO SECURE THE AMOUNT OF REPAIRS THERETO. IT IS UNDERSTOOD THAT THIS COMPANY ASSUMES NO RESPONSIBILITY FOR LOSS, OR DAMAGE BY THEFT OR FIRE TO VEHICLES PLACED WITH THEM FOR STORAGE, SALE, REPAIR OR WHILE ROAD TESTING. DUE TO PROGRAM ERROR, DISREGARD HRS/QTY HEADING ABOVE \$75.00 PER DAY STORAGE FEE WILL BE CHARGED BEGINNING 5 DAYS AFTER NOTIFICATION OF COMPLETION OF REPAIRS.

SIGNED_

I ACKNOWLEDGE NOTICE AND ORAL APPROVAL OF INCREASE IN THE PRICE.

SIGNED

B.A.R. # AM129453 EPA # CAL 000271714 RETURN OLD PARTS. ____YES ____NO

A&S Powers				
Customer: <u>NATHAN</u> FEND Year / Make: <u>Og K / 300 G T</u>	E = m	VQ6 535	Ser	Milegge: 12 38
License Plate: 2052907				
	Customer Concerns:	18 K	BRA	LAE FWSH?
MARK VISIBLE DAMAGE		RECALL		
	To be completed by Tech		.9961	
		May Require Atten	tion Soon Req	uires Immediate Attention
	Front Tire T	read Rear Greater 0.4 mm or less Set to:		uid Levels Engine / Trans Oil Clutch Fluid Engine Coolant Front Brake Fluid Rear Brake Fluid
		ts Headlight Tail Light RT Signal LT Signal Other Lights	Additi Additi	ional Checks Belt / Chain Spokes / Wheels Battery Cables / Controls Luggage
		ks Engine Final Drive Coolant Fuel Forks	Additional N Neuk	otes: put put
	Torque FT,	$\frac{0}{0}$ % of front left	Technician: Customer Sic Date:	p. 4 gaeture: 15/11