

# A&S MOTORCYCLE PARTS, INC.

1125A Orlando Ave.  
Roseville, CA 95661-  
(800)689-9893

# Repair Order

R/O Number: 999059505

In Date: 5/3/2011

Today Date: 5/5/2011

Date Promised: 5/3/2011

Repair Order For:

Unit Name

Location

NATHAN W.

**Units for this Repair Order**

Service Writer: JEFF HANRAHAN

| Year | Make | Model   | VIN / Serial No.  | Color | Plate | Key Board | Miles |
|------|------|---------|-------------------|-------|-------|-----------|-------|
| 2006 | BMW  | R1200GS | WB10317A86ZR41015 | RED   |       | 414       | 39649 |

**Job: OIL CHANGE**

Job For: 2006 BMW R1200GS WB10317A86ZR41015

**Description**

C/S WOULD LIKE AN OIL CHANGE

**Parts**

| Part Number           | Quantity | Description                  | Each Price | Extension      |
|-----------------------|----------|------------------------------|------------|----------------|
| 541OIL                | 1        | OIL CHANGE SPECIAL HEX HEADS | \$18.78    | \$18.78        |
| <b>Parts Subtotal</b> |          |                              |            | <b>\$18.78</b> |

**Labor**

| Description           | Job Code | Technician      | Quantity   | Line Total     |
|-----------------------|----------|-----------------|------------|----------------|
| OIL CHANGE            |          | RYAN HILDEBRAND | 0.22 Hours | \$21.17        |
| <b>Labor Subtotal</b> |          |                 |            | <b>\$21.17</b> |

**Recommendations**

**Resolution**

TECH RENEWED OIL AND FILTER

**Other Charges**

Hazmat Fee \$4.00

**Job Subtotal \$43.95**

**Job: TRANSMISSION OUTPUT SEAL (WESTERN AUTH 9084721)**

Job For: 2006 BMW R1200GS WB10317A86ZR41015

**Description**

C/S OIL LEAK AROUND TRANSMISSION OUTPUT SHAFT.

**Parts**

| Part Number           | Quantity | Description | Each Price | Extension      |
|-----------------------|----------|-------------|------------|----------------|
| 23127705087           | 1        | SHAFT SEAL  | \$15.92    | \$15.92        |
| <b>Parts Subtotal</b> |          |             |            | <b>\$15.92</b> |

# A&S MOTORCYCLE PARTS,

1125A Orlando Ave.  
Roseville, CA 95661-  
(800)689-9893

# Repair Order Deposit

R/O Number: 999059505

Ticket Number: 99681483

Cashier: JEFF HANRAHAN

Date: 5/5/2011

## Customer

 NATHAN W.  
  


---

Method Of Payment: SRVC-CASH

Payment Amount: \$45.50

Description

Notes:

5/5/2011 6:09:37 PM

# A&S POWERSPORTS Multi-Point Safety Inspection

Customer: Nathan [REDACTED] E-mail: \_\_\_\_\_ Service Advisor: \_\_\_\_\_  
 Year / Make: \_\_\_\_\_ VIN #: ZR41015 Color: \_\_\_\_\_ Mileage: 39649  
 License Plate: 18M5833 Date: \_\_\_\_\_ R.O. #: \_\_\_\_\_ Pick-Up: \_\_\_\_\_

Customer Concerns: \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

**MARK VISIBLE DAMAGE**

To be completed by Technician

Checked & OK     May Require Attention Soon     Requires Immediate Attention

| Front                                | Tire Tread     | Rear                             | Fluid Levels  |
|--------------------------------------|----------------|----------------------------------|---|
| <input checked="" type="radio"/>     | 5mm or Greater | <input checked="" type="radio"/> | <input checked="" type="radio"/> Engine / Trans Oil |
| <input checked="" type="radio"/>     | 3mm to 4 mm    | <input checked="" type="radio"/> | <input checked="" type="radio"/> Clutch Fluid       |
| <input checked="" type="radio"/>     | 2mm or less    | <input checked="" type="radio"/> | <input checked="" type="radio"/> Engine Coolant     |
| Front PSI: @ _____ Set to: <u>36</u> |                |                                  | <input checked="" type="radio"/> Front Brake Fluid  |
| Rear PSI: @ _____ Set to: <u>42</u>  |                |                                  | <input checked="" type="radio"/> Rear Brake Fluid   |

| Lights  | Additional Checks                                  |
|---|--|
| <input checked="" type="radio"/> Headlight    | <input checked="" type="radio"/> Belt / Chain      |
| <input checked="" type="radio"/> Tail Light   | <input checked="" type="radio"/> Spokes / Wheels   |
| <input checked="" type="radio"/> RT Signal    | <input checked="" type="radio"/> Battery           |
| <input checked="" type="radio"/> LT Signal    | <input checked="" type="radio"/> Cables / Controls |
| <input checked="" type="radio"/> Other Lights | <input checked="" type="radio"/> Luggage           |

| Leaks  |
|--|
| <input checked="" type="radio"/> Engine      |
| <input checked="" type="radio"/> Final Drive |
| <input checked="" type="radio"/> Coolant     |
| <input checked="" type="radio"/> Fuel        |
| <input checked="" type="radio"/> Forks       |

| Brakes   |
|--|
| <input checked="" type="radio"/> <u>OK</u> % of front left |
| <input checked="" type="radio"/> <u>OK</u> % of rear left  |
| Torque   |
| <input checked="" type="radio"/> FT/RR Caliper Bolts       |
| <input checked="" type="radio"/> FT/RR Wheel Mount         |
| <input checked="" type="radio"/> Oil Drain Plugs           |

Additional Notes:  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

Technician: RY

Customer Signature: \_\_\_\_\_

Date: 5/5/11

